

# ISO 22514-7:2021 (E)

## Statistical methods in process management — Capability and performance — Part 7: Capability of measurement processes

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Symbols and abbreviated terms
4.1	Symbols
4.2	Abbreviated terms
5	Basic principles
5.1	General
5.2	Resolution
5.3	Maximum permissible error known and used
5.3.1	General
5.3.2	MPE, maximum permissible deviation of the measuring system — $u_{MPE}$
5.4	Capability and performance limits for a measuring system and measurement process
6	Implementation
6.1	General
6.2	Factors that influence the measurement process
6.2.1	General
6.2.2	Uncertainty components that belong to the measuring system
6.2.2.1	Types
6.2.2.2	Estimation of uncertainty using the maximum permissible error value
6.2.2.3	Measuring system resolution
6.2.2.4	Calculation of repeatability, bias and linearity using reference standards or calibrated workpieces
6.2.2.5	Experimental method
6.2.3	Additional uncertainty components belonging to the measurement process
6.2.3.1	General
6.2.3.2	Determination of uncertainty components from experiments (Type A)
6.2.3.3	Determination of uncertainty components not included in the experiments (Type B)
6.2.3.4	Impact of the deviation of workpiece on the measurement result
6.2.3.5	Resolution
6.2.3.6	Temperature influence
6.2.3.6.1	Uncertainty calculation
6.2.3.6.2	Uncertainty component caused by temperature differences and expansion
6.2.3.6.3	Uncertainty on the coefficient of expansion
7	Studies for calculating the uncertainty components
7.1	Measuring system
7.1.1	General
7.1.2	Repeatability and bias based on one reference standard
7.1.2.1	General
7.1.2.2	Preconditions
7.1.2.3	Procedure
7.1.3	Standard uncertainty from the linearity deviation — $u_{LIN}$
7.1.3.1	Applicable methods

7.1.3.2	Method B
7.1.3.3	Method A
7.1.3.4	Linearity evaluation with ANOVA
<b>8</b>	<b>Calculation of combined uncertainty</b>
8.1	General
8.2	Calculation of expanded uncertainty
<b>9</b>	<b>Capability</b>
9.1	Performance ratios
9.1.1	General
9.1.2	Performance ratio of the measuring system
9.1.3	Performance ratio of the measurement process
9.2	Capability indices
9.3	Capability of a measurement process with one-sided specifications
<b>10</b>	<b>Capability of the measurement process compared to the capability of the production process</b>
10.1	Relation between observed process capability and measurement capability ratios
10.2	Relation between observed process capability and measurement capability
<b>11</b>	<b>Ongoing review of the measurement process stability</b>
11.1	Ongoing review of the stability
<b>12</b>	<b>Capability of attribute measurement processes</b>
12.1	General
12.2	Capability calculations without using reference values
12.3	Capability calculations using reference values
12.3.1	Calculation of the uncertainty range
12.3.2	Symbols
12.3.3	Working steps for determining the uncertainty range
12.4	Ongoing review
<b>Annex A (informative) Examples</b>	
A.1	Example of linearity study with at least three standards
A.1.1	General
A.1.2	Calculation of means and residuals
A.1.3	ANOVA table:
A.1.4	Estimation of uncertainty components
A.2	Experimental determination of the measurement process uncertainty
A.3	Determination of the uncertainty components not taken into account by experiments
A.4	Determination of the combined and expanded uncertainty
A.5	Assessing the capability of the measuring system and measurement process
<b>Annex B (informative) Statistical methods used</b>	
B.1	F-test
B.2	ANOVA tables
B.3	Relation between capability of the measurement process and capability of the production process