

# ISO 30007:2010-12 (E)

## Ships and marine technology - Measures to prevent asbestos emission and exposure during ship recycling

---

| <b>Contents</b>    |  | <b>Page</b> |
|--------------------|--|-------------|
| Foreword .....     |  | iv          |
| <b>1</b>           | <b>Scope .....</b>   | <b>1</b>    |
| <b>2</b>           | <b>Terms and definitions .....</b>   | <b>1</b>    |
| <b>3</b>           | <b>Work categorization (grade) to minimize asbestos emissions and exposure during ship recycling .....</b> | <b>2</b>    |
| <b>4</b>           | <b>Preliminary check for asbestos-containing materials .....</b>   | <b>3</b>    |
| <b>5</b>           | <b>Planning removal of ACM .....</b>   | <b>3</b>    |
| 5.1                | General .....  | 3           |
| 5.2                | Operational overview .....   | 3           |
| 5.3                | Organizational chart for managing asbestos removal .....   | 3           |
| 5.4                | Operating schedule .....   | 3           |
| 5.5                | Removal written plan .....   | 3           |
| 5.6                | Asbestos-monitoring plan .....   | 4           |
| 5.7                | Waste disposal plan .....  | 4           |
| <b>6</b>           | <b>Work procedures for each work grade .....</b>   | <b>4</b>    |
| 6.1                | General .....  | 4           |
| 6.2                | Work grade 1 .....   | 4           |
| 6.3                | Work grade 2 .....   | 10          |
| 6.4                | Work grade 3 .....   | 12          |
| 6.5                | Considerations for asbestos insulation piping .....  | 14          |
| Bibliography ..... |  | 15          |