

ISO 18941:2011-12 (E)

Imaging materials - Colour reflection prints - Test method for ozone gas fading stability

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Requirements	3
5	Target selection	3
6	Measurements	3
6.1	Use of replicates and reference samples	3
6.2	Holding and measurement conditions	4
6.3	Measured attributes	5
7	Calculations and computations	6
7.1	Computation of densitometric attributes	6
7.2	Density change in dmin patches	6
7.3	Percentage density change in primary colour patches	6
7.4	Percentage density change in secondary (mixed) colour patches	6
7.5	Percentage density change in composite neutral patch	6
7.6	Colour balance shift in composite neutral patch	6
7.7	Colour balance shift in secondary (mixed) colour patches	7
7.8	Colour balance in dmin patches by colorimetry	7
7.9	Effects of colorant fading and stain formation on colour photographs	7
8	Test methods -- Gas fading (ozone)	7
8.1	General	7
8.2	Apparatus	7
8.3	Test procedure	14
9	Test environment conditions	15
9.1	Humidity control calibration	15
9.2	Relative humidity	15
9.3	Temperature	15
9.4	Ozone concentration	15
10	Test report	16
10.1	General reporting requirements	16
10.2	Ozone test reporting	16
Annex A (informative) Method for interpolation		18
Annex B (normative) Reciprocity considerations		19
Bibliography		21