

ISO 2721:2013-03 (E)

Photography - Film-based cameras - Automatic controls of exposure

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Specific requirements	2
4.1	Scales	2
4.2	Out-of-range indication	2
4.3	The sensors of exposure controls	2
5	Calibration of the exposure controls	3
5.1	Method of calibration	3
5.2	Light source for calibration	3
5.3	General test conditions	3
5.4	Exposure in the focal plane	4
6	Acceptance angles of the photoelectric system	4
6.1	Specific acceptance angle	4
6.2	Oblique acceptance angles	4
Annex A (normative)	Measurement of light exposure in the focal plane and calibration of measuring instrument	5
Annex B (normative)	Size of measuring area	8
Annex C (normative)	Performance test	9
Bibliography		11