

ISO/TR 18931:2001-06 (E)

Imaging materials - Recommendations for humidity measurement and control

| Contents | | Page |
|--|--|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 Scope | | 1 |
| 2 Terms and definitions | | 1 |
| 3 Moisture content of gases | | 2 |
| 4 Measuring systems | | 2 |
| 5 Sensor location | | 5 |
| 6 Recommendations | | 5 |
| Annex A Importance of relative humidity | | 6 |
| Annex B Humidity control in storage areas | | 7 |
| Bibliography | | 8 |