

# ISO 3070-3:2007-12 (E)

## Machine tools - Test conditions for testing the accuracy of boring and milling machines with horizontal spindle - Part 3: Machines with movable column and movable table

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terminology and designation of axes .....</b>	<b>2</b>
<b>4</b>	<b>Definition of the machining operations carried out on these machines .....</b>	<b>3</b>
4.1	Boring operations .....	3
4.2	Milling operations .....	4
<b>5</b>	<b>Special remarks concerning particular elements .....</b>	<b>4</b>
5.1	Spindle heads .....	4
5.2	Tables .....	5
5.3	Steady blocks .....	5
<b>6</b>	<b>Preliminary remarks .....</b>	<b>5</b>
6.1	Measuring units .....	5
6.2	Reference to ISO 230-1 .....	5
6.3	Testing sequence .....	5
6.4	Tests to be performed .....	5
6.5	Measuring instruments .....	6
6.6	Machining tests .....	6
6.7	Software compensation .....	6
6.8	Minimum tolerance .....	6
<b>7</b>	<b>Geometric tests .....</b>	<b>7</b>
7.1	Straightness and angular deviations of coordinate axes .....	7
7.2	Squareness between coordinate axes .....	15
7.3	Table .....	17
7.4	Indexing or rotary table .....	20
7.5	Boring spindle .....	23
7.6	Milling spindle .....	29
7.7	Ram .....	30
7.8	Integral facing head .....	33
7.9	Steady block .....	37
<b>8</b>	<b>Machining tests .....</b>	<b>38</b>
<b>9</b>	<b>Checking accuracy and repeatability of positioning by numerical control .....</b>	<b>45</b>
<b>10</b>	<b>Geometric accuracy of axes of rotation of tool-holding spindles .....</b>	<b>51</b>
Bibliography .....		53