

ISO 23125:2010-05 (E)

Machine tools - Safety - Turning machines

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	2
3	Terms and definitions	5
3.1	General terms	5
3.2	Parts of turning machines	6
3.3	Modes of operation	7
3.4	Size and groups of turning machines defined in this International Standard	8
3.4.1	General	8
3.5	Mandatory and optional modes of operation for turning machines	14
3.6	Maximum permissible spindle speeds and axes feeds	14
4	List of significant hazards	15
4.1	Main hazard zones	15
4.2	Significant hazards and hazardous situations covered by this International Standard	16
5	Safety requirements and/or measures	21
5.1	General requirements	21
5.1.1	Required characteristics for guards for all machine groups	21
5.2	Specific requirements resulting from mechanical hazards identified in Clause 4	22
5.2.1	Group 1 machines	22
5.2.2	Groups 2, 3 and 4 machines	23
5.2.3	Workpiece clamping conditions	26
5.2.4	Modes of machine operation	27
5.2.5	Optional or additional equipment for turning machines	31
5.3	Specific requirements resulting from electrical hazards	33
5.4	Specific requirements resulting from noise hazards	34
5.5	Specific requirements resulting from radiation hazards	34
5.6	Specific requirements resulting from material or substance hazards	34
5.7	Specific requirements resulting from neglect of ergonomic principles hazards	35
5.8	Specific requirements resulting from unexpected start-up, over-run or over-speed hazards	37
5.9	Specific requirements resulting from variation in the rotational speed of tools hazards	39
5.10	Specific requirements resulting from failure of the power supply hazards	39
5.11	Specific requirements resulting from failure of the control circuit hazards	39
5.12	Specific requirements resulting from errors of fitting hazards	41
5.13	Specific requirements resulting from ejected fluids or objects hazards	41
5.13.1	General requirements	41
5.13.2	Guards for large vertical Group 3 machines (NC turning machines and turning centres) ..	42
5.13.3	Guards for large horizontal Group 3 machines (NC turning machines and turning centres)	42
5.14	Specific requirements resulting from loss of stability hazards	43
5.15	Specific requirements resulting from slips, trips and fall of persons hazards	43
5.16	Verification of the safety requirements and/or protective measures	43
6	Information for use	46
6.1	Marking	46

6.2	Instruction for use	46
6.2.1	General	46
6.2.2	Tooling	48
6.2.3	Workpiece clamping	48
6.2.4	Machine functions accessible from the NC panel	49
6.2.5	Restart	49
6.2.6	Noise	49
6.2.7	Ancillary handling devices	50
6.2.8	Residual risks to be addressed by the machinery user	50
6.2.9	Installation instructions for the turning machine	51
6.2.10	Cleaning instruction for the machine	51
Annex A (normative) Impact test method for guards on turning machines		52
Annex B (informative) Test equipment for impact test and examples of materials		57
Annex C (informative) Calculation of direct impact energy		60
Annex D (informative) Example of check list for safety functions		62
Annex E (informative) Examples of exhaust and extinguishing systems		64
Annex F (informative) Example of the determination of performance level for interlocked guard		68
Bibliography		73