

# ISO 230-3:2020 (E)

## Test code for machine tools — Part 3: Determination of thermal effects

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Preliminary remarks
4.1	Measuring units
4.2	Reference to ISO 230-1
4.3	Recommended instrumentation and test equipment
4.4	Machine tool conditions prior to testing
4.5	Testing sequence
4.6	Test environment temperature
4.7	Uncertainty due to temperature effects
5	Environmental temperature variation error (ETVE) test
5.1	General
5.2	Test method
5.3	Interpretation of results
5.4	Presentation of results
6	Thermal distortion caused by rotating spindle
6.1	General
6.2	Test method
6.3	Interpretation of results
6.4	Presentation of results
7	Thermal distortion caused by linear motion of components
7.1	General
7.2	Test method
7.2.1	Measurement positions
7.2.2	Setup of instruments
7.2.3	Test cycle
7.2.4	Temperature measurements
7.2.5	Compensations
7.3	Presentation of results
8	Thermal distortion due to rotary motion of components
8.1	General
8.2	Test method
8.2.1	Target positions
8.2.2	Test setup
8.2.3	Test cycle
8.2.4	Temperature measurements
8.2.5	Presentation of results
Annex A	(informative) Information on linear displacement sensors
A.1	General
A.2	Mechanical sensors
A.2.1	General

- A.2.2 Precautions in use
- A.3 Electronic sensors
  - A.3.1 General
  - A.3.2 Contact-type electronic sensors
    - A.3.2.1 General
    - A.3.2.2 Precautions in use
  - A.3.3 Non-contact-type electronic sensors
    - A.3.3.1 Eddy current sensors
      - A.3.3.1.1 General
      - A.3.3.1.2 Precautions in use
    - A.3.3.2 Capacitance sensors
      - A.3.3.2.1 General
      - A.3.3.2.2 Precautions in use
- A.4 Optical sensors
  - A.4.1 Laser optical triangulation measurement sensors
    - A.4.1.1 General
    - A.4.1.2 Precautions in use
  - A.4.2 Laser scanning micrometre
    - A.4.2.1 General
    - A.4.2.2 Precautions in use
- A.5 Temperature stability test for linear displacement sensors

**Annex B (informative) Guidelines on the required number of linear displacement sensors**

**Annex C (informative) Guidelines for machine tool thermal environment**

- C.1 General
- C.2 Flow rate and velocity
- C.3 Frequency and amplitude of temperature variations
- C.4 Mean temperature
- C.5 Temperature gradients

**Annex D (informative) Alternative measurement devices and set-ups**

- D.1 A device for measurements of ETVE and thermal distortion of structure caused by rotating spindle
- D.2 Alternative measurement set-ups for thermal distortion due to linear motion of components

Page count: 50