

# ISO 16090-1:2022-11 (E)

## Machine tools safety - Machining centres, milling machines, transfer machines - Part 1: Safety requirements

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b>		<b>v</b>
<b>Introduction</b>		<b>vi</b>
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>2</b>
<b>3</b>	<b>Terms and definitions</b>	<b>4</b>
3.1	General terms	4
3.2	Groups of machines	7
3.3	Parts of machines	8
3.4	Mode of operations	9
3.5	Maximum permissible spindle speed and feed rate	11
<b>4</b>	<b>List of significant hazards</b>	<b>11</b>
4.1	General	11
4.2	Main hazard zones	11
4.3	Significant hazards and hazardous situations covered by this document	12
<b>5</b>	<b>Safety requirements and/or protective/risk reduction measures</b>	<b>16</b>
5.1	General requirements	16
5.1.1	General	16
5.1.2	Guards requirements	16
5.1.3	Requirement for gravity loaded axes	19
5.2	Specific requirements resulting from mechanical hazards	19
5.2.1	Protective measures for Group 1 machines	19
5.2.2	Protective measures for Group 2 machines	19
5.2.3	Protective measures for Group 3 and Group 4 machines	20
5.2.4	Mode of operation (MO)	21
5.2.5	Optional or additional equipment for machines	28
5.3	Specific requirements resulting from electrical hazards	36
5.4	Specific requirements resulting from noise hazards	37
5.5	Specific requirements resulting from radiation hazards	37
5.6	Specific requirements resulting from material or substance hazards	37
5.6.1	Combustible coolants	37
5.6.2	Minimum quantity lubrication (MQL)	39
5.6.3	Dry processing and combustible dust	39
5.6.4	Requirements for biological or microbiological hazards	39
5.7	Specific requirements resulting from neglect of ergonomic principles hazards	40
5.8	Specific requirements resulting from failure or disorder of the control system	41
5.8.1	General	41
5.8.2	Starting	41
5.8.3	Normal stop	42
5.8.4	Emergency stop	42
5.8.5	Manual reset function	42
5.8.6	Safety related parts of control system (SRP/CS)	43
5.8.7	Monitoring rotational speed limits and limits of linear and rotary movements	44
5.8.8	Requirements for electromagnetic compatibility of electrical equipment	44
5.9	Specific requirements resulting from failure of any power supply	45
5.10	Specific requirements resulting from errors of fitting hazards	45
5.11	Specific requirements resulting from ejected fluids or parts	45
5.11.1	General requirements	45
5.11.2	Ejection of parts — Guard strength	46
5.11.3	Power-operated workpiece and tool clamping	46
5.11.4	Additional requirements for Group 3 and Group 4 machines	47
5.12	Specific requirements resulting from loss of stability hazards	47

5.13	Requirements resulting from slips, trips, and fall of persons hazards.....	47
5.14	Requirements resulting from accessibility for maintenance or troubleshooting on high parts of the machine.....	47
5.15	Requirements for machinery with operator cabins and perimeter fencing.....	47
5.15.1	General.....	47
5.15.2	Overall concept for entering/leaving machinery.....	48
5.15.3	Requirements for moveable/adjustable operator cabins and operation platforms.....	48
5.15.4	Requirements for perimeter fencing.....	51
5.16	Requirements for teleservice.....	51
5.17	Verification of the safety requirements and/or protective measures.....	51
<b>6</b>	<b>Information for use.....</b>	<b>56</b>
6.1	General.....	56
6.2	Marking.....	56
6.2.1	General markings.....	56
6.2.2	Symbols of operating modes (MO) on machines.....	57
6.3	Instruction for use.....	58
6.3.1	General.....	58
6.3.2	Tooling.....	60
6.3.3	Workpiece clamping.....	61
6.3.4	Machine functions accessible from the NC panel.....	61
6.3.5	Restart.....	61
6.3.6	Noise.....	61
6.3.7	Residual risks to be addressed to the machinery user.....	62
6.3.8	Installations instructions of machinery.....	63
6.3.9	Cleaning instructions of machinery.....	63
6.3.10	Machinery with operator cabins and/or perimeter fencing.....	63
6.3.11	Machinery equipped with gravity loaded axes or slant axes.....	63
6.3.12	Machinery equipped with MO 3.....	63
6.3.13	Machinery that is telecontrol-ready.....	64
	<b>Annex A (normative) Impact test method for guards on machines.....</b>	<b>65</b>
	<b>Annex B (informative) Equipment for impact test and examples of tested materials.....</b>	<b>68</b>
	<b>Annex C (informative) Illustrative figures as examples of machines.....</b>	<b>70</b>
	<b>Annex D (informative) Illustrative figures as examples of guards.....</b>	<b>79</b>
	<b>Annex E (informative) Examples of the integration of exhaust and extinguishing systems when using combustible coolants or combustible dust.....</b>	<b>86</b>
	<b>Annex F (informative) Provisions when using combustible coolants and combustible dust.....</b>	<b>88</b>
	<b>Annex G (normative) Gravity-loaded axes.....</b>	<b>91</b>
	<b>Annex H (informative) Examples: Concept for leaving/returning to a cabin (control station) at Group 3 and Group 4 machines.....</b>	<b>98</b>
	<b>Annex I (informative) Typical demand rates of safety functions for calculations according to <a href="#">Table 3</a> and <a href="#">Annex J</a>.....</b>	<b>100</b>
	<b>Annex J (normative) Safety functions.....</b>	<b>105</b>
	<b>Annex K (normative) Noise emission measurement.....</b>	<b>152</b>
	<b>Bibliography.....</b>	<b>154</b>