

# ISO 10791-2:2023-04 (E)

## Test conditions for machining centres - Part 2: Geometric tests for machines with vertical spindle (vertical Z-axis)

---

Contents	Page
<b>Foreword .....</b>	<b>v</b>
<b>Introduction .....</b>	<b>vii</b>
<b>1 Scope .....</b>	<b>1</b>
<b>2 Normative references .....</b>	<b>1</b>
<b>3 Terms and definitions .....</b>	<b>2</b>
<b>4 Preliminary remarks .....</b>	<b>2</b>
<b>4.1 Measurement units .....</b>	<b>2</b>
<b>4.2 Reference to the ISO 230 series .....</b>	<b>2</b>
<b>4.2.1 General .....</b>	<b>2</b>
<b>4.2.2 Consideration of relative measurements .....</b>	<b>2</b>
<b>4.3 Reference to ISO 10791-6 .....</b>	<b>2</b>
<b>4.4 Testing sequence .....</b>	<b>3</b>
<b>4.5 Tests to be performed .....</b>	<b>3</b>
<b>4.6 Tolerances .....</b>	<b>3</b>
<b>4.7 Measuring instruments .....</b>	<b>4</b>
<b>4.8 Diagrams .....</b>	<b>4</b>
<b>4.8.1 General .....</b>	<b>4</b>
<b>4.8.2 Alphabetic characters used for the E error expressions .....</b>	<b>4</b>
<b>4.8.3 Error direction .....</b>	<b>4</b>
<b>4.9 Pallets .....</b>	<b>5</b>
<b>4.10 Software compensation .....</b>	<b>5</b>
<b>4.11 Axes not under test .....</b>	<b>5</b>
<b>4.12 Machine configurations .....</b>	<b>5</b>
<b>4.13 Designation .....</b>	<b>6</b>
<b>5 Geometric tests .....</b>	<b>8</b>
<b>5.1 Straightness errors of linear motions .....</b>	<b>8</b>
<b>5.2 Angular errors of linear motions .....</b>	<b>11</b>
<b>5.3 Squareness errors between linear motions .....</b>	<b>16</b>
<b>5.4 Spindle .....</b>	<b>19</b>
<b>6 Horizontal non-rotating tables .....</b>	<b>24</b>
<b>7 Tables rotating around a vertical C'-axis .....</b>	<b>30</b>
<b>8 Tables rotating around a vertical C'-axis and tilting around a horizontal A'-axis .....</b>	<b>41</b>
<b>8.1 General .....</b>	<b>41</b>
<b>8.2 Tests for rotary tables tilting around the A'-axis .....</b>	<b>42</b>
<b>8.3 Tests for the A'-axis tilting from -90° to +90° .....</b>	<b>61</b>
<b>8.4 Tests for the A'-axis tilting from -90° to 0° .....</b>	<b>67</b>
<b>8.5 Tests for the A'-axis tilting from 0° to +90° .....</b>	<b>71</b>
<b>9 Tables rotating around a vertical C'-axis and tilting around a horizontal B'-axis .....</b>	<b>75</b>
<b>9.1 General .....</b>	<b>75</b>
<b>9.2 Tests for rotary tables tilting around the B'-axis .....</b>	<b>76</b>
<b>9.3 Tests for the B'-axis tilting from -90° to +90° .....</b>	<b>95</b>

9.4	Tests for the B'-axis tilting from -90° to 0° .....	100
9.5	Tests for the B'-axis tilting from 0° to +90° .....	104
<b>Annex A (informative) Tests for error motions of tool holding spindle and work holding rotary table axes related to Clauses 7, 8 and 9 .....</b>		<b>108</b>
<b>Annex B (informative) Tests for error motions of axes of rotation of tables rotating around a vertical C'-axis and tilting around a horizontal A'-axis related to Clause 8 .....</b>		<b>113</b>
<b>Annex C (informative) Tests for error motions of axes of rotation of tables rotating around a vertical C'-axis and tilting around a horizontal B'-axis related to Clause 9 .....</b>		<b>118</b>
<b>Bibliography .....</b>		<b>123</b>