

# DIN EN 16806-1:2016-07 (E)

## Textiles and textile products - Textiles containing phase change materials (PCM) - Part 1: Determination of the heat storage and release capacity

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Terms and definitions .....	4
4	Principle of test .....	5
5	Test equipment, reagents and materials .....	5
6	Test specimens .....	5
7	DSC test procedure .....	7
8	Calculation of test results .....	7
9	Test report .....	8
Bibliography .....		10