

# DIN EN ISO 3758:2024-04 (E)

## Textiles - Care labelling code using symbols (ISO 3758:2023 )

---

<b>Contents</b>	<b>Page</b>
European foreword.....	3
Foreword.....	4
Introduction.....	5
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Description and definition of symbols</b> .....	<b>8</b>
4.1 Symbols.....	8
4.1.1 General.....	8
4.1.2 Main symbols.....	8
4.1.3 Additional descriptives.....	10
4.2 Washing.....	11
4.3 Bleaching.....	13
4.4 Drying.....	13
4.4.1 General.....	13
4.4.2 Tumble drying.....	13
4.4.3 Natural drying.....	14
4.5 Ironing and pressing.....	15
4.6 Professional textile care.....	15
<b>5 Application and use of symbols</b> .....	<b>17</b>
5.1 Application of symbols.....	17
5.2 Characteristics and test methods for the selection of appropriate symbols.....	17
5.3 Use of symbols.....	17
<b>Annex A (informative) Characteristics and available test methods for the correct selection of care symbols</b> .....	<b>19</b>
<b>Annex B (informative) Regional and national requirements in care labelling</b> .....	<b>26</b>
<b>Annex C (informative) Examples of additional wording</b> .....	<b>27</b>
<b>Annex D (informative) Adaptation of registered graphical symbols for use in practice</b> .....	<b>28</b>
<b>Bibliography</b> .....	<b>35</b>