

IEC 63517:2026-06 (E)

Wearable electronic textiles - Test method for performance of heating products - Heating temperature and power consumption

Contents

Page

FOREWORD	2
INTRODUCTION	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Principle	6
5 Test equipment and materials	6
5.1 Thermometer	6
5.2 External power source	6
5.3 Measuring devices for voltage and current	6
5.4 Infrared thermographic camera	6
5.5 Thermal insulation	6
6 Test specimens	7
6.1 Conditioning	7
6.2 Preparation of test specimen	7
6.3 Selection of measuring points	7
7 Test procedure	8
7.1 Environmental conditions	8
7.2 Heating temperature	8
7.3 Power consumption for heating	9
8 Test report	10
Bibliography	11
Figure 1 – Preparation of test	7
Figure 2 – Selection of measuring points	8
Figure 3 – Test procedure of heating temperature	9
Figure 4 – Measurement of power consumption	10