

DIN EN ISO 11137-3:2017-11 (E)

Sterilization of health care products - Radiation - Part 3: Guidance on dosimetric aspects of development, validation and routine control (ISO 11137-3:2017)

Contents

Page

European foreword	4
Foreword	5
Introduction	6
1 Scope	7
2 Normative references	7
3 Terms, definitions and symbols	7
3.1 General	7
3.2 Symbols	9
4 Measurement of dose	10
4.1 General	10
4.1.1 Direct and indirect dose measurements	10
4.1.2 Dosimetry systems	10
4.1.3 Best estimate of dose	10
4.2 Dosimetry system selection and calibration	11
4.2.1 General	11
4.2.2 Selection of dosimetry systems	11
4.2.3 Calibration of dosimetry systems	11
4.3 Dose measurement uncertainty	12
4.3.1 General concepts	12
4.3.2 The Guide to the expression of uncertainty in measurement (GUM) methodology	12
4.3.3 Radiation sterilization specific aspects of dose measurement uncertainty	13
5 Establishing the maximum acceptable dose	14
6 Establishing the sterilization dose	15
7 Installation qualification	16
8 Operational qualification	17
8.1 General	17
8.2 Gamma irradiators	17
8.3 Electron beam irradiators	19
8.4 X-ray irradiators	21
9 Performance qualification	23
9.1 General	23
9.2 Gamma irradiators	24
9.2.1 Loading pattern	24
9.2.2 Dosimetry	25
9.2.3 Analysis of dose mapping data	26
9.3 Electron beam irradiators	26
9.3.1 Loading pattern	26
9.3.2 Dosimetry	28
9.3.3 Analysis of dose mapping data	29
9.4 X-ray irradiators	29
9.4.1 Loading pattern	29
9.4.2 Dosimetry	30
9.4.3 Analysis of dose mapping data	31

and control

10	Routine monitoring and control	31
10.1	General.....	31
10.2	Frequency of dose measurements.....	32
Annex A	(informative) Mathematical modelling.....	33
Annex B	(informative) Tables of references for dosimetry-related testing during IQ/OQ/PQ.....	36
Annex C	(informative) Tolerances associated with doses used in sterilization dose setting/ substantiation in ISO 11137-2 and ISO/TS 13004	39
Annex D	(informative) Application of dose measurement uncertainty in setting process target doses.....	40
Bibliography		46