

ISO 21734-1:2022-11 (E)

Intelligent transport systems - Performance testing for connectivity and safety functions of automated driving buses in public transport - Part 1: General framework

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
3.1	Terms and definitions	1
3.2	Abbreviated terms	5
4	General information	5
4.1	ISO 21734 series overview and structure	5
4.2	Purpose of the ISO 21734 series	6
5	ADB system Components	6
5.1	Overview	6
5.2	ADB component	6
5.3	MC centre component	7
5.4	IoT infrastructure component	7
5.5	Smart bus station component	7
5.6	ADB user component	7
6	ADB system framework	8
6.1	Overview	8
6.2	Safety aspect of ADB system framework	8
6.2.1	General	8
6.2.2	Road infrastructure	8
6.2.3	Safety performance test elements of the ADB operation	9
6.3	Connectivity aspect of the ADB system framework	10
6.3.1	General	10
6.3.2	Connectivity infrastructure	10
6.3.3	Connectivity performance test elements of ADB operation	11
6.4	ADB system framework requirements	12
6.4.1	ADB component requirements	12
6.4.2	MC centre component requirements	13
6.4.3	IoT infrastructure requirements	16
6.4.4	Smart bus station requirements	16
6.4.5	ADB user requirements	17
6.5	ADB service framework	18
7	Required data sets	19
7.1	General	19
7.2	Operation	20
7.2.1	Signalized intersection case	20
7.2.2	Crosswalk case	21
7.2.3	Bus stop case	22
7.3	ADB service	23
8	Use cases	25

8.1	General	25
8.2	Left turn on intersection	25
8.2.1	Use case 1-1: Protected left turn on intersection	25
8.2.2	Use case 1-2: Permitted left turn on intersection	26
8.3	Straight forward on intersection	27
8.3.1	Use case 2: Straight forward on intersection	27
8.4	Right turn on intersection	28
8.4.1	Use case 3-1: Right turn on intersection	28
8.4.2	Use case 3-2: Right turn on red on intersection	29
8.5	Crosswalk	30
8.5.1	Use case 4-1: Signalized pedestrian crosswalk	30
8.5.2	Use case 4-2: Non-signalized pedestrian crosswalk	31
8.6	Smart bus station	32
8.6.1	Use case 5-1: Bus station with bay	32
8.6.2	Use case 5-2: Bus station without bay	33
Bibliography		35