

DIN EN ISO 20769-1:2018-12 (E)

Non-destructive testing - Radiographic inspection of corrosion and deposits in pipes by X- and gamma rays - Part 1: Tangential radiographic inspection (ISO 20769-1:2018)

Contents	Page
Foreword	5
7.8.1 Measurements for internal degradation	27
7.8.2 Measurements for external degradation	29
8 Digital image recording, storage, processing and viewing	21
8.1 Scan and read out of image	21
8.2 Multi radiograph technique	21
8.3 Calibration of DDAs	21
8.4 Bad pixel interpolation	21
8.5 Image processing	21
8.6 Digital image recording and storage	21
8.7 Monitor viewing conditions	22
9 Test report	22
Annex A (informative) Choice of radiation source for different pipes	34
Annex B (informative) Remaining thickness measurements for internal degradation	35
Annex C (informative) Remaining thickness measurements for external degradation	38
Bibliography	42
7.7 Wall thickness measurements for digital radiographs	26
7.7.1 Interactive on-screen measurements	26
7.7.2 Grey-level profile analysis methods	26
7.8 Remaining thickness measurements for degradation	27