

# DIN EN ISO 20769-1:2018-12 (E)

Non-destructive testing - Radiographic inspection of corrosion and deposits in pipes by X- and gamma rays - Part 1: Tangential radiographic inspection (ISO 20769-1:2018)

---

| <b>Contents</b>   | <b>Page</b> |
|---|-------------|
| Foreword .....  | 5           |
| 7.8.1 Measurements for internal degradation .....                                     | 27          |
| 7.8.2 Measurements for external degradation .....                                     | 29          |
| 8 Digital image recording, storage, processing and viewing .....                      | 21          |
| 8.1 Scan and read out of image .....  | 21          |
| 8.2 Multi radiograph technique .....  | 21          |
| 8.3 Calibration of DDAs .....   | 21          |
| 8.4 Bad pixel interpolation .....   | 21          |
| 8.5 Image processing .....  | 21          |
| 8.6 Digital image recording and storage .....   | 21          |
| 8.7 Monitor viewing conditions .....  | 22          |
| 9 Test report .....   | 22          |
| Annex A (informative) Choice of radiation source for different pipes .....            | 34          |
| Annex B (informative) Remaining thickness measurements for internal degradation ..... | 35          |
| Annex C (informative) Remaining thickness measurements for external degradation ..... | 38          |
| Bibliography .....  | 42          |
| 7.7 Wall thickness measurements for digital radiographs .....                         | 26          |
| 7.7.1 Interactive on-screen measurements .....  | 26          |
| 7.7.2 Grey-level profile analysis methods .....                                       | 26          |
| 7.8 Remaining thickness measurements for degradation .....                            | 27          |