

DIN EN ISO 20769-2:2018-12 (E)

Non-destructive testing - Radiographic inspection of corrosion and deposits in pipes by X- and gamma rays - Part 2: Double wall radiographic inspection (ISO 20769-2:2018)

Contents		Page
Foreword		5
8.6	Key points	25
9	Digital image recording, storage, processing and viewing	25
9.1	Scan and read out of image	25
9.2	Calibration of DDAs	25
9.3	Bad pixel interpolation	25
9.4	Image processing	26
9.5	Digital image recording and storage	26
9.6	Monitor viewing conditions	26
10	Test report	26
Annex A (normative)	Minimum image quality values	28
Annex B (normative)	Penetrated thickness measurements from image grey levels	30
Annex C (normative)	Determination of basic spatial resolution	32
Bibliography		35
8.3	Source and detector positioning	24
8.4	Image grey level profiles	24
8.5	Validation	24