DIN EN ISO 20769-1:2018-12 (E)

Non-destructive testing - Radiographic inspection of corrosion and deposits i n pipes by X- and gamma rays - Part 1: Tangential radiographic inspection (ISO 20769-1:2018)

Contents

Page

Foreword 5

7.8.1 Measurements for internal degradation 27
7.8.2 Measurements for external degradation 29

8 Digital image recording, storage, processing and viewing 21
8.1 Scan and read out of image 21
8.2 Multi radiograph technique 21
8.3 Calibration of DDAs 21
8.4 Bad pixel interpolation 21
8.5 Image processing 21
8.6 Digital image recording and storage 21
8.7 Monitor viewing conditions 22

9 Test report 22

Annex A (informative) Choice of radiation source for different pipes 34

Annex B (informative)Remainingthicknessmeasurementsforinternaldegradation 35

Annex C (informative)Remainingthicknessmeasurementsforexternaldegradation 38

Bibliography 42

7.7 Wall thickness measurements for digital radiographs 26
7.7.1 Interactive on-screen measurements 26
7.7.2 Grey-level profile analysis methods 26
7.8 Remaining thickness measurements for degradation 27