DIN EN ISO 20769-2:2018-12 (E)

Non-destructive testing - Radiographic inspection of corrosion and deposits in pipes by X- and gamma rays - Part 2: Double wall radiographic inspection (ISO 20769-2:2018)

Contents

Page

Foreword 5

8.6 Key points 25

9 Digital image recording, storage, processing and viewing 25
9.1 Scan and read out of image 25
9.2 Calibration of DDAs 25
9.3 Bad pixel interpolation 25
9.4 Image processing 26
9.5 Digital image recording and storage 26
9.6 Monitor viewing conditions 26

10 Test report 26

Annex A (normative)Minimumimagequalityvalues 28

Annex B (normative)Penetratedthicknessmeasurementsfromimagegreylevels 30

Annex C (normative) Determination of basic spatial resolution 32

Bibliography 35

8.3 Source and detector positioning 24
8.4 Image grey level profiles 24
8.5 Validation 24